635487

## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

$\sim$	ATTH	TT	TORI	mr	
Jυ	MT.	TT	$\mathbf{H}$	TI	AL

COUNTRY	China	REPORT NO.	25X1A	
SUBJECT	Highway Repair, Changchou, Fukien	DATE DISTR.	25 May 1954	
DATE OF INFO. PLACE ACQUIRED	25X1A	NO. OF PAGES REQUIREMENT NO. REFERENCES	1 RD	
THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE.  THE APPRAISAL OF CONTENT IS TENTATIVE.  (FOR KEY SEE REVERSE)				

- 1. On 20 March 1954, the Chinese Communists began repairing the highway between Changchou (N 24-32, E 117-42) and Chiaowei (N 24-32, E 117-56). The road surface was broadened to nine meters and the shoulders were increased to two meters in width. An aggregate of crushed stone, sand and dirt was added to the surface. Mechanical road rollers were being used. Laborers were working daily on the road.
- On 23 March, three mechanical road rollers left Changchou in the direction of Chiaowei.

25X1A